Control of X10 devices with LOR is done via a CM-11A controller. You will have to do some looking around for this if you don't already own it (eBay is a great source). The newer CM-15A will NOT WORK (as of 10/29/2005) with LOR. Dan has hinted that CM-15A support might be part of LOR II.