

When updating the firmware on a DC-MP3 card, you may encounter this error. If you are using a version of the Hardware Utility (HWU) prior to 1.5.10 then you will need update to the most recent HWU.