

There are 4 components you will need to get started.

1. A controller.
2. The software to run the controller.
3. A serial or USB adapter.
4. A CAT5 cable to transmit the signal to your LOR board.

So, to simplify that even more, you need the following to items from the Light-O-Rama site. SPK-ST Outdoor Showtime Starter Package (Note that as of 09/16/2005, you get a free Cat5 cable with your purchase.)